

# Home Improvements

**Property Address:  
71 Barrington Drive, Bedford, NH**

## **2022**

- Resealed driveway
- Replaced gas insert for both the primary bedroom and living room fireplaces
- New Frigidaire microwave in island
- Updated kitchen lighting
- Repainted front door
- Repainted foyer, main level hallways and second floor hallway
- Repainted primary bathroom
- Repainted bedroom above mudroom
- Repainted Jack and Jill bath
- New pool filter cartridges
- Repainted garage

## **2021**

- Refinished hardwood floors main level
- Replaced carpets in all bedrooms
- New Bosc dishwasher
- Repainted kitchen and family room
- Repainted living room/bar area
- Replaced main level furnace

## **2020**

- Updated home audio system to Sonos
- New Wolf double oven
- New Sta-Rite pool pump installed for swimming pool
- Repainted bedroom, closet and ensuite bath above office/guestroom

## **2019**

- New Hot Springs Pulse Limelight Hot Tub
- Retiled and acid washed gunite swimming pool
- Repainted bedroom above dining room

## **2017**

- Replaced second floor and basement level furnace